

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(860) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:	SITE NO.:		
UTM: 18/	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL POTENTIAL

IDENTIFICATION

1. BUILDING NAME: Common: Calvary Baptist Church of New Haven Historic: _____
2. TOWN/CITY: New Haven VILLAGE: _____ COUNTY: New Haven
3. STREET & NUMBER (and/or location): 100 Dwight Street
4. OWNER(S): Calvary Baptist Church of New Haven PUBLIC PRIVATE _____
5. USE: Present: Religious Historic: Same
6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain Church Services no

DESCRIPTION

7. STYLE OF BUILDING: Contemporary DATE OF CONSTRUCTION: ca. 1960
8. MATERIAL(S) (indicate use or location when appropriate):
 ___ clapboard ___ asbestos siding ___ brick
 ___ wood shingle ___ asphalt siding ___ fieldstone
 ___ board & batten ___ stucco ___ cobblestone
 ___ aluminum siding concrete: type: poured cut stone: type: _____
 ___ other: _____ (foundation)
9. STRUCTURAL SYSTEM:
 ___ wood frame: ___ post and beam ___ balloon
 load bearing masonry ___ structural iron or steel
 ___ other: _____
10. ROOF: type:
 ___ gable flat ___ mansard ___ monitor ___ sawtooth
 ___ gambrel ___ shed ___ hip ___ round ___ other _____
 material:
 ___ wood shingle ___ roll asphalt ___ tin ___ slate
 ___ asphalt shingle ___ built up ___ tile ___ other: _____
11. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: 40' x 60'
12. CONDITION: Structural: excellent ___ good ___ fair ___ deteriorated
 Exterior: excellent ___ good ___ fair ___ deteriorated
13. INTEGRITY: Location: on original site ___ moved, when: _____
 Alterations: no ___ yes, explain: _____
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 ___ barn ___ shed ___ garage ___ other landscape features or buildings: _____
 ___ carriage house ___ shop ___ garden _____
15. SURROUNDING ENVIRONMENT:
 ___ open land ___ woodland residential ___ scattered buildings visible from site
 ___ commercial ___ industrial ___ rural ___ high building density
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

The church is bordered to the north by the Embassy Arms Apartments and to the south by the yard of the corner residence.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

This white, cut-stone church is rectangular in plan with a 3 storey tower on the southeast corner. Adjacent to the tower on the front (east) facade is the entrance. The double steel doorway has transom above and sidelights. A concrete overhang surmounts this with a large plate glass light above. The remainder of the facade is uninterrupted except by a wooden cross. A band of smooth square concrete blocks cap the walls.

The north elevation has a projecting steel frame bay which supports a wall of concrete into which are set pieces of stained glass.

SIGNIFICANCE

Architect: _____ Builder: _____


18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

PHOTOGRAPH

photographer: Thomas Hahn
date: Summer, 1979 view: Southeast corner
negative on file: CHC; CTHP

COMPILED BY:

name: Lannie Hoglund date: Fall, 1979
organization: Connecticut Trust for Historic Preservation
address: 152 Temple Street, New Haven, Connecticut 06510



19. SOURCES:

Maps and Atlases
New Haven City Directories

20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____