STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106 (203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

TOWN NO.:		SITE NO.:	
UTM: 18/_	//_	/_	//_
QUAD:		,	
TOND.			
DISTRICT:	s	NR:	ACTUAL

IDENTIFICATION	
1. BUILDING NAME: Common:	Historic:
2. TOWN/CITY: New Haven VILLAGE	: COUNTY: New Haven
3. STREET & NUMBER (and/or location):	19 Howe - Outbuilding
4. OWNER(S): Offices	PUBLIC PRIVAT
5. USE: Present: Offices	Historic: Carriage House
6. ACCESSIBILITY TO PUBLIC: Exterior visible fr Interior accessible	om public road: X yes no : X yes, explain Clinic n
7. STYLE OF BUILDING: Queen Anne	DATE OF CONSTRUCTION: 1885/1971
8. MATERIAL(S) (indicate use or location when application	ding X brick ling fieldstone cobblestone
9. STRUCTURAL SYSTEM: wood frame:post and beamballoonx load bearing masonrystructuralother:	
10. ROOF: type: X gableflat mansardgambrelshedhip material:wood shingleroll asphalttin	monitor sawtooth other slate
X asphalt shinglebuilt up tile	other:
11. NUMBER OF STORIES: 1½ APPR	OXIMATE DIMENSIONS: 40' x 40'
12. CONDITION: Structural: $\frac{X}{X}$ excellent Exterior: $\frac{X}{X}$ excellent	good fair deteriorated good fair deteriorated
13. INTEGRITY: Location: $\frac{X}{X}$ on original site move Alterations: $\frac{X}{X}$ on $\frac{X}{X}$ yes, explain:	ed, when: See over
14. RELATED OUTBUILDINGS OR LANDSCAPE Ibarnshed garagecarriage houseshop garden	EATURES: X_other landscape features or buildings: House at 19 Howe Street
15. SURROUNDING ENVIRONMENT: open landwoodlandX residentiaindustrial rural	X scattered buildings visible from site high building density
16. INTERRELATIONSHIP OF BUILDING AND SU	RROUNDINGS:

This building, originally the carriage house of 19 Howe Street, sits directly east of that building, separated by a 100' parking lot. A brick apartment building stands of its southwest corner. It sits 30' from North Frontage Road, fronting it (south), and beside a high rise apartment complex and extensive parking lot on the east.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

SIGNIFICANCE

This $1\frac{1}{2}$ storey brick carriage house has been extensively renovated but retains its basic form. Square in plan, it has a steep broad gable roof with a low cupola which is louvred and capped by a finial. A hoist beam projects from the gable end above the center opening, larges of 3 original bays (now with plate glass) with bluestone sills and segmental arches. The 3 odd-sized vehicle bays now hold lights with frame infill. A solid brick cylinder of cornice-level height stands off the building's southwest corner and is joined to it by a glass corridor which also contains the main entrance. A 2nd entrance has been added in a glass panel of cornice height on the west wall. Inside several skylights illuminate the large center space which is open to the roof.

Address Environmental Decies (1971) 2 114
Architect: Environmental Design Group (1971) Builder: 18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:
Part of the Sherman Foote complex (see 19 Howe Street), this carriage house originally was reached by a 15' wide drive which led the 300' from Oak Street to it and 2 garages of neighboring estates. A substantial structure, its re-use (especially
in connection with its parent house) is exemplary from a preservationist and architectural view. It is hoped that its current, 2nd interior renovation will complement the original wonders of light and space.
PHOTOGRAPH
photographer: Thomas Hahn date: Fall, 1979 view: South elevation negative on file. CHC; CTHP
COMPILED BY: name: Sandra Lee date: 9/19/79 organization: Connecticut Trust for Historic Preservation address: 152 Temple Street, New Haven, Connecticut 06510
19. SOURCES:
Maps and Atlases New Haven City Directories
Brown pp. 28, 80
20. SUBSEQUENT FIELD EVALUATIONS:
21. THREATS TO BUILDING OR SITE: none knownhighways vandalismdevelopers other:renewalprivateX deteriorationzoning explanation: sandblasted inside and out