STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106 (203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

| LON NWOT | | SITE NO.: | | | | |
|-----------|-----|-----------|--------|--|--|--|
| UTM: 18/_ | //- | / | // | | | |
| QUAD: | | , | | | | |
| QUAD: | | | | | | |
| DISTRICT: | \$ | NR: | ACTUAL | | | |

| IDENTIFICATION | Hartford Natio | onal Bank | | 0 | |
|--|---|---------------|------------------------------|---------------|---------------------------------------|
| 1. BUILDING NAME: Common: | and Trust Comp | pany | Historic: | Same | |
| 2. TOWN/CITY: New Haven | VILLAGE: | | C | OUNTY: | New_Haven |
| 3. STREET & NUMBER (and/or lo | ocation): | 130 Park | Street | | |
| 4. OWNER(S): Park and | George Associates | | | | PUBLIC X PRIVATE |
| 5. USE: Present: Bank | | Histori | c: Same | | |
| 6. ACCESSIBILITY TO PUBLIC: | Exterior visible from place \underline{x} | oublic road:_ | x yes no | rs admit | tedno |
| DESCRIPTION | | | | | |
| 7. STYLE OF BUILDING: | Contemporary | D | ATE OF CO | NSTRUC | TION: 1960 |
| 8. MATERIAL(S) (indicate use orclapboardwood shingleboard & battenaluminum sidingX_other: tile | location when approp asbestos siding asphalt siding stucco concrete: type | g | bri fie co cu | ldstone | pe: |
| 9. STRUCTURAL SYSTEM: wood frame:post and beaxload bearing masonryother: | structural iron | or steel | | | |
| 10. ROOF: type: gableXflatgambrelshed material:wood shingleroll asphal | lt tin | round | ot | wtooth her | · · · · · · · · · · · · · · · · · · · |
| asphalt shingleYoult up | tile | other: | | | · · · · · · · · · · · · · · · · · · · |
| 11. NUMBER OF STORIES: 2 | APPROXI | IMATE DIM | ENSIONS: | 50' x 4 | 0. |
| 12. CONDITION: Structural: Exterior: | $\frac{X}{X}$ excellent | good good | fa fa | ir ir . | <pre> deteriorated deteriorated</pre> |
| 13. INTEGRITY: Location: <u>x</u> on c Alterations: <u>x</u> no | original site moved, oyes, explain: | | | | |
| 14. RELATED OUTBUILDINGS Obarnshedcarriage houseshop | | TURES: | ndscape feat | tures or bu | ildings: |
| 15. SURROUNDING ENVIRONMED open landwoodlandindustrial | X residential | | d buildings ilding densit | | n site |
| 16. INTERRELATIONSHIP OF BU | JILDING AND SURR | COUNDINGS | 5: | | |

Part of a neighborhood of mixed use residential and commercial buildings, this bank's facade (east) fronts Park Street. Bordered to the west by its property line, this building is bordered to the south by its parking lot and the north by a similarly scaled

structure.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

This 2 storey flat-roofed building is rectangular in plan with a south side wing and drive in teller's booth. The building is sheathed with square, pink tile. The fenestrated facade features 3 bays of tinted glass windows on the 2nd floor. The lst floor features a center display window with prominent sign above. The inset glass door entrance is located on the north side. The building is sheathed with decorative applied fiberglass panelling along its cornice and spaced between its windows.

There is not the first state

| Application of the application o | A Section of the sect | and the state of t | or transport Although the Line of the |
|--|--|--|--|
| and the second of the second o | الله در الا الله الله عليه الله الله | CT CONTROL OF THE PROPERTY OF | The second secon |
| the P | 1 1/0/2 <u>%</u> | at a see a group of a contract of the contract | in the second of |
| GNIFICANCE | y to take a party | รมาศักม์เสียกตร คนีสาม. ผม | The state of the s |
| Architect: | | Builder: | a design to a second map of the second maps to the |
| 8. HISTORICAL OR ARCHITECTUR | | | 1000 |
| A relatively undisting | rished modern | commercial build | ling, little outstanding |
| architectural merit is appare | ent. Its lands | scaped lot and v | vell kept appearance howeve |
| render it an asset to its son | ewhat deterior | cating surround | ings. |
| , w | | | 1. 15 11 11 11 |
| medical control of the second | | Townson | |
| maga alikus da | | ** ** *** *** *** *** | The state of the s |
| IOTOGRAPH | | The College of | |
| photographer: Thomas Hahn date: Summer, 1979 view: S | | | |
| 077.0 | outheast corne | er | |
| negative on file: CHC; CTHP | | 1,000 | |
| OMPILED BY: | | The Park Comment of the Pa | |
| name: Mariko Masuoka/Sandra I | ee date: | Fall. 1979 | |
| organization: Connecticut Trust fo | | 1 | |
| address: 152 Temple Street, New | Haven, Connec | ticut***06510 | |
| | Mar State | A. A | |
| 9. SOURCES: | San San San San San | | |
| Maps and Atlases | Ya. It | 72 | Company of the Compan |
| New Haven City Directories | ESALT STALLS | | |
| the second secon | | Taker, managemental | and the second s |
| and the second s | 38.4.4 | un a areas e Maria. Un responsable | |
| O. SUBSEQUENT FIELD EVALUATI | ONS: | estate estate | |
| | ' A " A | " (Miss) | MANAZ MANAZ ILA A SEZ |
| programme and the state of the | · · · · · · · · · · · · · · · · · · · | 1.0 | 10 0000 |
| And the second s | er - Agricultur (| Last and the | All Control of the Co |
| | | Segretario de Partir de La Caraca de La Cara | on I see out |
| | A Comment of the Comm | Last and the | |
| | | | |
| en e | Agricultural of the second of | ing the second of the second o | |
| 1. THREATS TO BUILDING OR SITI | | | |
| 21. THREATS TO BUILDING OR SITI | | developers | |