

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:		SITE NO.:	
UTM: 18/	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL POTENTIAL

IDENTIFICATION

1. BUILDING NAME: Common: Chapel Medical Center Historic: _____
2. TOWN/CITY: New Haven VILLAGE: ----- COUNTY: New Haven
3. STREET & NUMBER (and/or location): 1423 Chapel Street
4. OWNER(S): Edward L. Harcus, Irvine B. Korman, Donald B. Alderman PUBLIC PRIVATE
5. USE: Present: Professional Offices Historic: Same
6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain _____ no

DESCRIPTION

7. STYLE OF BUILDING: Contemporary DATE OF CONSTRUCTION: ca. 1970
8. MATERIAL(S) (indicate use or location when appropriate):
 ___ clapboard ___ asbestos siding brick beige
 ___ wood shingle ___ asphalt siding ___ fieldstone
 ___ board & batten ___ stucco ___ cobblestone
 ___ aluminum siding ___ concrete: type: _____ ___ cut stone: type: _____
 ___ other: _____
9. STRUCTURAL SYSTEM:
 ___ wood frame: ___ post and beam ___ balloon
 load bearing masonry ___ structural iron or steel
 ___ other: _____
10. ROOF: type:
 ___ gable flat ___ mansard ___ monitor ___ sawtooth
 ___ gambrel ___ shed ___ hip ___ round ___ other _____
 material:
 ___ wood shingle ___ roll asphalt ___ tin ___ slate
 ___ asphalt shingle ___ built up ___ tile ___ other: _____
11. NUMBER OF STORIES: 3 APPROXIMATE DIMENSIONS: 60' x 100'
12. CONDITION: Structural: excellent ___ good ___ fair ___ deteriorated
 Exterior: excellent ___ good ___ fair ___ deteriorated
13. INTEGRITY: Location: on original site ___ moved, when: _____
 Alterations: no ___ yes, explain: _____
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 ___ barn ___ shed ___ garage ___ other landscape features or buildings: _____
 ___ carriage house ___ shop ___ garden _____
15. SURROUNDING ENVIRONMENT:
 ___ open land ___ woodland residential ___ scattered buildings visible from site
 commercial ___ industrial ___ rural ___ high building density
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

This building stands in a very well-landscaped yard across Chapel Street from St. Raphael's Hospital.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

This large rectangular building is 3 storeys tall. A 4-storey marble-faced stair tower edged by narrow, continuous vertical window strips forms the building's southwest corner and its only facade opening. Limestone strips create a cornice line and vertical striping on the beige brick wall surface.

SIGNIFICANCE

Architect: _____

Builder: _____

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

Though very well-kept, this building provides little or no architectural interest.

PHOTOGRAPH

photographer: Thomas Hahn

date: Fall, 1979 view: Southeast corner

negative on file: CHC:CTWP


COMPILED BY:

name: Sandra Lee

date: 11/30/79

organization: Connecticut Trust for Historic Preservation

address: 152 Temple Street, New Haven, Connecticut 06510



19. SOURCES:

Maps and Atlases

New Haven City Directories

20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____