

CONNECTICUT HISTORICAL COMMISSION

79 South Prospect Street, Hartford, Connecticut 06106

(3) 566-3005

**HISTORIC RESOURCES INVENTORY FORM**

For Buildings and Structures

## FOR OFFICE USE ONLY

TOWN NO.: \_\_\_\_\_ SITE NO.: \_\_\_\_\_

UTM: 18/---/---/---/---/---/---

QUAD: \_\_\_\_\_

DISTRICT: \_\_\_\_\_ S NR: \_\_\_\_\_ ACTUAL  
POTENTIALIDENTIFICATION

Holy Trinity Church of

1. BUILDING NAME: Common: God in Christ Historic: \_\_\_\_\_2. TOWN/CITY: New Haven VILLAGE: \_\_\_\_\_ COUNTY: New Haven3. STREET & NUMBER (and/or location): 85 Greenwood Street4. OWNER(S): State of Connecticut PUBLIC X PRIVATE5. USE: Present: Religious Historic: Same6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: X yes no  
Interior accessible: X yes, explain Church services noDESCRIPTION7. STYLE OF BUILDING: Contemporary DATE OF CONSTRUCTION: ca. 1970

8. MATERIAL(S) (indicate use or location when appropriate):

<input type="checkbox"/> clapboard	<input type="checkbox"/> asbestos siding	<input checked="" type="checkbox"/> brick facade facing
<input type="checkbox"/> wood shingle	<input type="checkbox"/> asphalt siding	<input type="checkbox"/> fieldstone
<input type="checkbox"/> board & batten	<input type="checkbox"/> stucco	<input type="checkbox"/> cobblestone
<input type="checkbox"/> aluminum siding	<input checked="" type="checkbox"/> concrete: type: <u>block</u>	<input type="checkbox"/> cut stone: type: _____
<input type="checkbox"/> other: _____		

9. STRUCTURAL SYSTEM:

wood frame:  post and beam  balloon  
 load bearing masonry  structural iron or steel  
 other: \_\_\_\_\_

10. ROOF: type:

gable  flat  mansard  monitor  sawtooth  
 gambrel  shed  hip  round  other \_\_\_\_\_

material:

wood shingle  roll asphalt  tin  slate  
 asphalt shingle  built up  tile  other: \_\_\_\_\_

11. NUMBER OF STORIES: 1 APPROXIMATE DIMENSIONS: 40' x 60'12. CONDITION: Structural:  excellent  good  fair  deteriorated  
Exterior:  excellent  good to  fair  deteriorated13. INTEGRITY: Location:  on original site  moved, when: \_\_\_\_\_  
Alterations:  no  yes, explain: \_\_\_\_\_

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:

barn  shed  garage  other landscape features or buildings: \_\_\_\_\_  
 carriage house  shop  garden \_\_\_\_\_

15. SURROUNDING ENVIRONMENT:

open land  woodland  residential  scattered buildings visible from site  
 commercial  industrial  rural  high building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

This building is isolated from the 2 others on the block, and from the Dwight Area as a whole by overgrown lots which surround it on every side.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

This single storey building consists of a 1 bay gabled body with double leaf door and 2 lower flat-roofed wings, 1 bay wide, with small windows.

SIGNIFICANCE

Architect: \_\_\_\_\_ Builder: \_\_\_\_\_

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

This building is architecturally undistinguished and visually isolated from neighborhoods to the north (Dwight Area) and South (the Hill). It is, however, evidently in regular use. The church moved here from Legion Avenue in 1971. The congregation first appears in the City Directory in 1967.

PHOTOGRAPH

photographer: Thomas Hahn  
date: Fall, 1979 view: West elevation  
negative on file: CHC; CTRP



COMPILED BY:

name: Sandra Lee date: 10/20/79  
organization: Connecticut Trust for Historic Preservation  
address: 152 Temple Street, New Haven, Connecticut 06510

19. SOURCES:

Maps and Atlases  
New Haven City Directories

20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known  highways  vandalism  developers  other: \_\_\_\_\_  
 renewal  private  deterioration  zoning  explanation: \_\_\_\_\_