STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

South Prospect Street, Hartford, Connecticut 06106

south and east are unpaved parking lots.

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

TOWN NO.:			E NO.:
UTM: 18/_	//_	<u> </u>	//
QUAD:		,	
	-	NR:	ACTUAL
DISTRICT:	3	IAIA.	ACIDAL

IDENTIFICATION	, , , , , , , , , , , , , , , , , , ,		
1. BUILDING NAME: Common:	Mamoun's Restau	Historic:	
2. TOWN/CITY: New Haven			Y: <u>New Haven</u>
3. STREET & NUMBER (and/or lo	cation):	85 Howe Street	
4.OWNER(S): Windsor R			PUBLIC X PRIVATE
5. USE: Present: Restauran		Historic: Commercial	
6. ACCESSIBILITY TO PUBLIC: I		public road X yes no yes, explain Customers	admitted no
DESCRIPTION			
7. STYLE OF BUILDING:	Commercial Vernac	ular DATE OF CONSTRU	JCTION: ca. 1950
8. MATERIAL(S) (indicate use or language o	location when approp asbestos siding asphalt siding stucco _X concrete: type	g brick fac fieldstone cobblesto	;
9. STRUCTURAL SYSTEM:wood frame:post and bea X_load bearing masonryother:	mballoon structural iron	or steel	
10. ROOF: type: gable		monitor sawtooth other slate other:	
11. NUMBER OF STORIES: 1	APPROX	IMATE DIMENSIONS: 40' x	30'
12. CONDITION: Structural: Exterior:	excellent excellent	$\frac{X}{X}$ good ${}$ fair fair.	deteriorated deteriorated
13. INTEGRITY: Location: X on o		when:nt facade re-faced	
14. RELATED OUTBUILDINGS Obarnshedcarriage houseshop	R LANDSCAPE FEA garage garden		buildings:
15. SURROUNDING ENVIRONMEopen landwoodland _X commercialindustrial	residential rural	scattered buildings visible f high building density	rom site
6. INTERRELATIONSHIP OF BL	ILDING AND SURR	OUNDINGS:	

This building stands in a mixed use street of buildings of various scales. To the

17 OTHER	RNOTABLI	E FEATU	IRES OF	BUILDING (OR SITE (int	erior and/or	avtarine).

	F BUILDING OR SITE (interior and/or	
This 1 storey building	is rectangular in plan and has	accenter entrance with
flanking plate lights.		Principle Property Company
- A was take to the transfer of the second o	t various defen	Per etaso Perentes de deserva
The company of the contract of	Volume 1 to 1 to 1	Service and the service of the servi
	· ·	
		Service Service Annual Company
The second secon		
Live Asia	12.174 2.274	
- 1 m		
	The december Thornesses	voe nit
the same and the	tantari, mang per sakirangangangan yar magantai dalamang asahilihihikinan samadasan sa sa sa sa sa sa 1923 B. Said	managed (Miller popular part)
SIGNIFICANCE	mile control year of the control of	A management of the control of the c
Architect	Builder	Territory and the second
18 HISTORICAL OR ARCHITECTUR	AL IMPORTANCE:	
This commercial building	ng is made less austere by its r	wide awning.
	tallestatist Extististic	
-	in the state of the organization	The first of the section .
Market St. Communication of the Communication of th	green will see the state of the	Lakerski L
	والمرابية والمعادية المعادية	
And the state of t		
PHOTOGRAPH photographer: Thomas Hahn		
date: Fall, 1979 view: V	Vest elevation	
negative on file: CHC; CTHP	na na mara mana mana mana mana mana mana	
COMPILED BY:	HIND AND BOOK ACTIVIDATED TO THE	
name: Mark Schlenker/Sandra I	Lee date: 10/20/79	
organization: Connecticut Trust fo		
address: 152 Temple Street, New	Haven, Connecticut 06510	
19. SOURCES:	ALL THE STATE OF T	
Maps and Atlases	100 march 100 ma	
New Haven City Directories		A PROPERTY OF THE PROPERTY OF
And the second of the second o	The state of the s	
materials to the second		The material system control
20. SUBSEQUENT FIELD EVALUATION	ONS:	1913 G
المنظمين المنظم الم والمنظم المنظم المنظ	A STATE OF THE STA	San District of Sales Sales Sales

20.

21. THREATS TO BU	JILDING OR SI	TE:	- V -	1757 Same	THE CALL YOUR
Xnone known	highways "	vandalism vandalism	developers	other:	the state of the s
renewal	private	deterioration		explanation:	