

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:		SITE NO.:	
UTM: 18	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL
			POTENTIAL

IDENTIFICATION

- 1. BUILDING NAME: Common: _____ Historic: _____
- 2. TOWN/CITY: New Haven VILLAGE: _____ COUNTY: New Haven
- 3. STREET & NUMBER (and/or location): _____ 425 George Street
- 4. OWNER(S): Weller Funeral Home, Incorporated PUBLIC PRIVATE
- 5. USE: Present: Funeral Home Historic: Same
- 6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain Clients admitted no

DESCRIPTION

- 7. STYLE OF BUILDING: Commercial Vernacular DATE OF CONSTRUCTION: ca. 1965
- 8. MATERIAL(S) (indicate use or location when appropriate):

<input type="checkbox"/> clapboard	<input type="checkbox"/> asbestos siding	<input checked="" type="checkbox"/> brick
<input type="checkbox"/> wood shingle	<input type="checkbox"/> asphalt siding	<input type="checkbox"/> fieldstone
<input type="checkbox"/> board & batten	<input type="checkbox"/> stucco	<input type="checkbox"/> cobblestone
<input type="checkbox"/> aluminum siding	<input type="checkbox"/> concrete: type: _____	<input type="checkbox"/> cut stone: type: _____
<input type="checkbox"/> other: _____		
- 9. STRUCTURAL SYSTEM:
 wood frame; post and beam balloon
 load bearing masonry structural iron or steel
 other: _____
- 10. ROOF: type:
 gable flat mansard monitor sawtooth
 gambrel shed hip round other _____
material:
 wood shingle roll asphalt tin slate
 asphalt shingle built up tile other: _____
- 11. NUMBER OF STORIES: 1 APPROXIMATE DIMENSIONS: 100' x 50'
- 12. CONDITION: Structural: excellent good fair deteriorated
Exterior: excellent good fair deteriorated
- 13. INTEGRITY: Location: on original site moved, when: _____
Alterations: no yes, explain: _____
- 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 barn shed garage other landscape features or buildings: _____
 carriage house shop garden large rear parking lot
- 15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density
- 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

This building occupies a large lot on this mixed use block. It is surrounded by a large paved parking lot and is bordered to the east by an abandoned house, and to the west by a house converted to multi-family use.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

This rectangular shaped building with rear "L" is windowless and has an entrance on the west end of its front facade.

SIGNIFICANCE

Architect: _____ Builder: _____

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

This building is well maintained and relieved by plantings in front. Its large presence in the middle of the block does sever the residential continuity which would otherwise exist here. At the same time it is a stable feature in a deteriorating block which is heavily trafficked.

PHOTOGRAPH

photographer: Thomas Hahn
 date: Fall, 1979 view: South elevation
 negative on file: CHC; CTHP

COMPILED BY:

name: Sandra Lee date: 10/1/79
 organization: Connecticut Trust for Historic Preservation
 address: 152 Temple Street, New Haven, Connecticut 06510



19. SOURCES:

Maps and Atlases
 New Haven City Directories

20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____